



**Fig. 4.** Hood lock being released using special tool. C moved for clarity.



B7774-S7583

Grille shown re-